


Modification to 2003-2005 KTM 950 Adventure to install BDCW new style side stand mount

A small portion of the frame just below the shifter needs to be removed – easily accomplished with a grinder in a few minutes. Be sure to treat the frame with some type of paint or sealant to prevent rust.

BEFORE PHOTOS



Modification to 2003-2005 KTM 950 Adventure to install BDCW new style side stand mount

AFTER PHOTOS:

Trimming complete

IMPORTANT: Ensure that the frame piece is trimmed enough to allow the BDCW Side Stand Mount to lay flat against the vertical framework pictured here.

*** DO NOT CUT OR MODIFY THE BDCW SIDE STAND MOUNT ***



Underside view of trimming complete



New BDCW side stand mount installed

**Notice applied sealant to prevent rust

